	Incident	Date Reported	Date of Mfg.	Weather: Date of incident, temp. in ferenheit n/a=not available	Weight of Trigger Pull	Alt.	CND	Rem Case	Serial Number	PDF	Property Damage	Comments	Wanted gun replaced, or did not want gun
1	FSR	11/29/2013	12/1/1970	n/a	Trigger Broken		Missin g	329125	6397837	30206			
2	FBC	4/17/2014	1/17/1973		3#		n/a	343581	6612261	35967			
3	FBC	11/18/2010	12/21/2007	n/a	5#		N	210778	7833281	15334			
4	FSR	2/11/2013	4/15/2008	n/a	2#		Missin g	300196	7834863	29785			
5	Fired w/o pulling trigger	2/9/2015	1/10/2008		4.5#		N	491977	7835125	40061			
											Shot hole in couch and floor. Remington paid him		Owner said he wanted Remingon to
6	FBC	9/17/2014	4/25/2008		2.5#		N	466342	7836497	39687	\$1,500		buy back rifle
7	FSR	1/10/2012	3/26/2009	n/a	3.5		N	253351	7839275	25563			

											Shot hole in		
											roof of		
							Missin				shooting		
8	FSR	11/24/2009	4/1/2009		Missing		g	181116	7839611	10360	shed.		
-		,,,	., _, _ = = = =										
9	FBC	12/18/2014	8/20/2010		2.5#		n/a	481293	7841363	39888			
10	FSR	8/21/2013	1/21/2008	n/a	3.5		N	318743	G6720076	29853			
	Unexplained		,										
11	Discharge	10/3/2014	n/a		5.5		N	469896	D6251282	36197		Has video	
12	FSR	1/28/2015	2/7/2007		3.5		N	488846	D6626347	40049			
	1 511	1,20,2013	2,7,2007		3.3		.,	100010	50020317	100 13			
							Missin						
13	FSR	11/12/2013	9/2/2009	n/a	Missing		g	Missing	D6636342	29900			
14	FSR	3/13/2014	9/2/2009		3#		N	340523	D6636342	35785			
				,									
15	FSR	11/16/2010	4/21/2010	n/a	4#		N	210518	D6638848	15301			
													OWNER
													DEMANDED A
						Altered							FULL REFUND
						trigger							FOR THE RIFLE
				11/11/2010Leb		adjustm							BECAUSE HE
				anon, MO 36 to		ent						Hurt trigger	NO LONGER
16	FSR	11/11/2010	7/13/2010	54 degrees	5#	screw	N	212997	D6641057	15349		finger	TRUSTED IT.
				Ŭ								<u> </u>	
	Fired without												
17	pulling the trigger	12/4/2012	5/13/2011	n/a	4.5#		N	291342	D6643129	25729			

												1
18	FSR	1/27/2014	6/24/2011		3.5		N	335507	D6644672	36325		
19	FSR	1/6/2015	6/24/2011		3.5#		N	483751	D6644672	40480		
20	FBC	1/3/2012	8/16/2011	n/a	3.5#		N	252201	D6645764	25630		
												Owner said he
												does not want
21	FSR	3/2/2015	2/3/2012		4#		N	494674	D6647759	39974		the rifle back.
22	FSR	10/16/2013	6/1/2011	n/a	3#		N	324125	D7008723	29961		
23	FSR	10/3/2011	1/22/1998	n/a	4.5#		N	242414	E6432762	25315		
						Stock						
						altered,						
						interfer red with						
24	FBC	3/10/2008	8/2/2001	n/a	3#	safety	N	142767	E6766865	20356		
						Custom						
						er					Changed	
						change d					trigger	
						trigger					assembly,	
	50.0	2/42/2022	0 /2 /2004	,	2.11	assembl		4.407.5-		DC 00000	but not	
25	FBC	3/10/2008	8/2/2001	n/a	3#	у	N	142767	E6766865	PSO9930	stock.	

ſ						Missi	n				
26	FSR	12/17/2013	1/2/2007	n/a	Missing	g	Missing	F6301681	29898		
				3/27/2010Mr.							
				Thomas says it							
27	FBC	4/20/2011	1/18/2005	was very cold.	2#	N	229380	G6456340	20630		
										Sent the	
										rifle back	
28	FSR	1/8/2010	6/12/2006	n/a	3.5#	N	185269	G6587737	10880	twice.	
20	1311	1/0/2010	0/12/2000	11/ 4	3.5#	11	103203	00307737	10000	Cut his	
										thumb on	
										the safety	
										when gun	
29	FSR	3/12/2008	10/24/2006		3.5#	N	142386	G6619050	9389	went off	
Ī											
						Missi					
30	FSR	2/23/2011	12/12/2006	n/a	2#	g	224073	G6628546	20168		
										l I	
										Happened	
				11/28/2011loca		Missi				four times on different	
31	FSR	2/22/2012	12/11/2006	tion unknown	1.5		259626	C6639607	25371	dates.	
31	ron	2/23/2012	12/11/2006	tion unknown	1.5	g	239020	G6628607	255/1	uates.	
						Missi	,				
32	FSR	10/23/2013	12/11/2006	n/a	1.5#	g	324990	G6630198	29822		
Ì	-		, , ,	, ,							
										Happened	
										twice when	
										gun was	
33	FSR	3/4/2009	12/12/2006		n/a	N	163852	G66315599	9334	loaded.	
34	FSR	8/15/2008	12/18/2006		4#	N	149335	G6634351	9374		

						Blocker						
						adjuste	Missin				Blocker	
35	FSR	8/8/2008	1/16/2007	n/a	3 1/4 #	d	g	148948	G6636738	PSO9338	adjusted	
36	FBC	2/28/2012	1/24/2007	n/a	3#		N	260200	G6639586	25818		
				·								
							Missin					
37	FSR	12/14/2012	1/24/2007	n/a	2#		g	292979	G6639605	26041		
38	FBC	1/22/2015	2/28/2007		5#		N	487080	G6640274	40134		
39	FSR	1/6/2011	1/18/2007	n/a	2.5#		N	217771	G6641633	20007		
39	1 311	1/0/2011	1/18/2007	11/ a	2.5#		IN	21///1	00041033	20007		
40	FSR	1/27/2012	2/19/2007	n/a	3#		N	256517	G6642544	25774		
	Fired w/o pulling											
41	trigger	2/10/2015	3/9/2007		3#		N	492364	G6648092	40040		
											Three incidents1	
42	FSE - FBC	10/17/2012	3/28/2007	n/a	5.5		N	285931	G6649951	25681	=FS2=FBC	
		-, , -	-, -,	, -								
43	FBC	7/29/2011	4/2/2007	n/a	3.5#		N	236915	G6652686	25423		
43	I DC	1/23/2011	4/2/200/	ii/ d	3.3#		IN	230313	00032000	23423		
							Missin					
44	Slam fires	3/8/2011	5/22/2007	n/a	2#		g	225161	G6658197	20622		

	_										
45	FBC	1/24/2011	5/15/2007	n/a	4.5#	N	220358	G6658917	19957		
		, ,	, ,	,							
46	FSR	1/10/2011	5/16/2007	n/a	3.5	N	128193	G6660557	19892		
47	Slam fires	10/20/2011	10/1/2007	n/a	4#	N	243961	G6663449	25493		
47	Sidili liles	10/20/2011	10/1/2007	11/ a	411	IN	243301	00003443	23433		
										Happened	
										five times in	
										a row. Put	
										the gun in a	
										freezer, and	
										it didn't	
		0.44.40.04.5	0/7/0005	,						happen	
48	FSR	2/4/2011	6/7/2007	n/a	3.5#	N	221999	G6665890	20082	again.	
49	FSR	2/16/2011	6/20/2007	n/a	5#	N	223387	G6667118	19940		
43	ran	2/10/2011	0/20/2007	11/ a	5#	IN	223307	0000/118	13340		
	Fired w/o pulling										
50	trigger	2/24/2015	6/23/2007		3.5#	n/a	493899	G6669783	40124		

ſ												OWNER
												STATES HE
												DOES NOT
												WANT THE GUN BACK
												BECAUSE HE
				Warm 60's or								DOES NOT
51	FSR	4/20/2011	7/20/2007	70's	3#	N	229386	G6673556	20669			TRUST IT.
ľ												
	Fired without											
52	pulling the trigger	1/21/2011	7/20/2007	n/a	3.5	N	220150	G6674403	19975			
53	FSR	12/17/2009	8/3/2007	n/a	4#	N	183050	G6674446	11007			
ľ												
										Shot a hole		
										in		
_,	Fired w/o pulling	12/20/2014	0 /0 /2007		2.4		404 400	66677275	20047	floorboard		
54	trigger	12/20/2014	8/8/2007		3#	N	481489	G6677375	39847	of truck		
				12/17/2010loca								
55	FSR	1/21/2011	8/9/2007	tion unknown	2.5	N	219965	G6680556	20583			
											Incident	
											occurred	
											multiple	
											times.	
											Significant	
											difference	
											in trigger	
											pull	
											between	
											cold and	
				2/44/2042 45							warm	
_	rcp.	2/20/2012	0/16/2007	2/11/2012 15	2.4	Missin	262442	CCC04222	35000		temperatur	
56	FSR	3/20/2012	8/16/2007	degrees F.	2#	g	262443	G6681222	25996		e.	

57	FSR	2/4/2015	9/6/2007		n/a		n/a	2/2	G6686865	40599	Shot hole in roof of deer blind.		
57	ron	2/4/2015	9/0/2007		n/a		II/a	n/a	G0000003	40599	deer biirid.		
58	FSR & FBC	1/10/2014	9/20/2007		1.5			333418	G6690360	35560			
		, -, -	-, -,		_								
59	FSR	2/7/2011	9/17/2007	n/a	1.5#		Missin g	222281	G6690902	20207			
60	FBC	12/2/2009	10/24/2007	n/a	2.5#	Trigger pull set below factory specs	N	181986	G6698737	11130		Trigger was replaced, and FBC happened again	
	.50	12, 2, 2003	20/2 1/2007	, ۵		3000		101000				~g	
61	Fired with safety on	1/3/2013	11/8/2007	n/a	4.5#		N	294889	G6701437	25780	Shot a hole in two walls of the house.		
62	FBC	1/4/2013	10/26/2007	n/a	4.5#		N	295116	G6702647	26030	Hole in folloboard and transmissio n of truck.		
02	TBC	1/4/2013	10/20/2007	11/ α	4.5#		IN	233110	G0702047	20030	II OI tiuck.		
63	FSR	8/1/2011	11/13/2007	n/a	4.5		N	236938	G6705329	25398			
64	Fired w/o pulling trigger	6/9/2008	12/6/2007		4.5		N	146229	G6709042	9378		Did not say when fired w/o pulling trigger	

ı				ı							1	
65	FSR	9/16/2009	2/21/2008	n/a	4.5#		N	175263	G671098	10599		
				,			Missin					
66	FSR	12/16/2011	12/21/2007	n/a	2#		g	250944	G6714589	25538		
67	Fired with safety on	1/19/2011	12/23/2007	n/a	5#		N	219692	G6714635	20033		
68	FDC	0/17/2014	1 /22 /2000		2#		N	466304	CC717CC	25007		
80	FRS	9/17/2014	1/23/2008		3#		N	466384	G6717665	35807		
		/2.2 /2.2	. / /									
69	FBC	11/20/2014	1/11/2008		2.5#		N	476988	G6717791	40552		
70	FSR	3/14/2014	1/25/2008		3#		N	340635	G6721685	36352		
	Fine describe a se											
71	Fired without touching the trigger	8/22/2014	2/18/2008		3#		N	460807	G6728815	35797		
	5											
72	FSR	12/12/2011	2/25/2008	n/a	2.25#		N	250010	G6730694	25469		
						Pull screw						
73	FSR	12/10/2010	2/22/2008	n/a	2.2#	altered	N	213756	G6730719	15232	 	
											Happened twice in	
											twice in December	
							Missin				2010very	
74	FSR & FBC	1/12/2011	2/27/2008	Cold +-0 degrees	2.5#		g	218561	G6732052	20127	cold.	

				,					T		
											Two
				Gun was out for							different
				one hour in the							shooters,
				Cold before							same
75	FSR	2/23/2010	3/13/2008	incident	2#		Ν	190134	G6733197	11037	results.
											Happened
											three times
											the same
76	FSR	9/16/2009	3/7/2008	n/a	4.5#		N	175244	G6733993	10916	day.
						Set					
						Screws					
77	FBC	12/17/2014	5/9/2008		6#	Altered	n/a	480758	G6734267	39669	
											Three
78	FSR	12/7/2011	4/1/2008	n/a	2#		Ν	248339	G6735887	25506	incidents.
											Required
											stitches
											from being
	Fired without										hit with
79	touching trigger	6/29/2014	3/11/2008		4#		N	431629	G6735933	35718	scope
80	FSR	1/17/2011	3/12/2008	n/a	4#		N	219235	G6736940	19990	
81	FBC	11/4/2014	3/14/2008		4#		N	473891	G6737474	40506	
						Trigger					
						pull					
82	FSR	12/16/2009	3/27/2008	n/a	2#	altered	N	183453	G6740364	10621	
83	FBC	8/11/2011	4/10/2008	n/a	4#		N	237730	G6743718	25500	
05	150	0/11/2011	7/ 10/ 2000	11/ 0	711		1.4	231130	30/73/10	23300	

84	Fired without pulling the trigger	7/15/2011	4/4/2008	n/a	5#	N	235733	G6744959	20613	Laid the gun down, and it fired.	
	Fired without										
	pulling the trigger										
	when laying gun										
85	down.	7/15/2011	4/4/2008	n/a	5#	N	235733	G6744959	25306		
				,							
86	FSR	12/3/2010	5/1/2008	n/a	4.5#	N	212435	G6751744	15467		
				,							
87	FSR	12/14/2011	5/1/2008	n/a	3.5	N	250418	G6752550	25513		
0.			3, 1, 1000	, &	0.0		200.20	0070200			
88	FSR	3/10/2015	5/13/2008		4#	N	495464	G6754724	40344		
		5, 25, 2525	2, 22, 222								
										Does not	
										want the	
89	FSR	3/2/2015	6/11/2008		5#	n/a	494556	G6764420	40316	rifle back.	
		0,2,2020	0, 11, 1000		<u> </u>	, ۵	.5 .555	30701120	.0010		
90	FBC	2/3/2009	6/27/2008		4.5#	N	160901	G6766012	9355		
	, _ ,	_, =, = = = =	5,21,255								
	Fired without										
	touching trigger										
	while lifting gun to									Two	
91	shoulder.	8/29/2011	7/24/2008	n/a	5#	N	239353	G6767445	25430	incidents	
71	Jilouluci.	0/23/2011	, , 27, 2000	11/ 4	511	14	233333	30/0/443	23430	HICIACITES	

			Ī									
92	FBC	6/17/2010	7/8/2008	n/a	2.5#		N	197441	G6768087	15311		
							Missis				Three	
93	FSR	4/4/2013	6/27/2008	n/a	Missing		Missin g	307049	G6770666	30233	incidents	
23	1310	4/4/2013	0/2//2008	11/ a	Wilssing		δ	307043	G0770000	30233	incidents	
											Damaged	
94	FBO FSR	6/6/2014	7/21/2008		4.5		N	418453	G6775567	36162	his truck	
95	FBC	4/16/2014	8/8/2008		4#		N	343450	G6779268	36307		
33	150	4, 10, 2014	0,0,2000		-711			343430	30773200	30307		
											Discharged	
	Unexplained										twice when	
96	Discharge	5/28/2014	8/11/2008		3#		N	413519	G6781297	36269	bumped	
						Trigger						
						pull set						
						below						
97	FBC	12/10/2011	8/29/2008	n/a	4#	min.	N	249813	G6782447	25462		
	Fired without											
98	pulling trigger	6/8/2011	8/29/2008	n/a	4#		N	233322	G6782459	20726		
30	panning tribber	0,0,2011	0,23,2000	11, 4			.,	255522	30702133	20720		
												OWNER
												WANTED
												REFUND. SAID
	500	2/20/2042	0/40/2002	. 1.	4.511		Missin	262226	66702000	25704		HE IS SCARED
99	FSR	3/28/2012	8/19/2008	n/a	1.5#		g	263330	G6782882	25791		OF GUN.

			1									
100	FBC	3/15/2010	8/18/2008	n/a	5.5#	N	191859	G6783559	10575			
101	FBC	2/4/2015	9/16/2008		5#	N	490171	G6791949	39879	Shot a hole in the wall of his house.		
102	FBC	2/4/2015	9/18/2008		5#	N	490123	G6795268	39856	Shot a hole in roof of truck.		
103	FSR	11/20/2014	9/22/2008		n/a	n/a	n/a	G6796649	40525		Owner refused to send gun to Remington.	
104	FSR	3/28/2014	9/23/2008		2#	N	341892	G6797063	35948			
105	FSR	12/19/2010	10/3/2008	n/a	4#	N	215411	G6801141	20119			
106	FBC	1/11/2013	10/1/2008	n/a	2.5#	N	296162	G6802371	29948			
	.30	-,, 2020	20, 2, 2000	.,, «		.,	255102	23320,1	233.0	Chan Th		OWNER ASKED FOR REFUND FOR THE RIFLE, AND
107	FBC	11/8/2010	10/13/2008	n/a	5#	N	209717	G6805477	15549	Shot TV and hole in the wall.		REMINGTON PAY FOR THE TV.
107	FDC	11/0/2010	10/13/2008	II/ a	J#	IV	203/1/	00003477	15549	tile wall.		IV.

400	Fired w/o pulling	F /7 /204 F	44/47/2000		4.54			400264	CC005745	405.64		
108	trigger	5/7/2015	11/17/2008		4.5#		N	499364	G6805715	40561		
											Fine d 2 and	
											Fired 2 out of 10 times	OWNER
											when taking	WANTS GUN
						Trigger Pull					off safety. Letter from	REPLACED. SAYS HE CAN
						Screw					Remington	NOT TRUST
109	FSR	1/7/2010	10/21/2008		2.5#	Altered	N	185068	G6809963	10541	apologizing	THIS GUN.
								279244/27	G6810666			
110	FBC	8/20/2012	1/7/2011	n/a	5.25		N	9232	G7031443	25849		
111	FSR	2/1/2011	1/9/2009	n/a	4#		N	221477	G6820005	20065		Т
112	FSR	10/12/2012	1/28/2009	n/a	3.5#		N	285297	G6830287	25651		
113	FBC	11/12/2012	3/23/2009	2/2	3#		N	288901	G6831210	26024		
113	FBC	11/12/2012	3/23/2009	n/a	3#		IN	288901	G0831210	26024		
											Two	
114	FBC	1/30/2013	1/21/2010	n/a	5#		N	298782	G6832556	29890	incidents	
	Fired w/o pulling											
115		12/12/2014	2/16/2009		4#		N	479540	G6835909	40363		

r		1				1						
							Missin					
116	FBC	12/11/2013	3/25/2009	n/a	7#		g	330531	G6837818	30179		
117	FBC	11/23/2011	2/11/2010	n /a	4#		N	247781	G6838361	25336		
11/	FBC	11/23/2011	2/11/2010	n/a	4#		IN	24//81	G0838301	25330		
											Owner says	
	Referenced Rem #										the rifle was	
	223671case not						Missin				not	
118	found			n/a	Missing		g	Re: 223671	G6839183	25945	repaired.	
							Missin					
119	FSR	12/11/2009	4/20/2009	n/a	Missing		g	182953	G6840518	10856		
							Missin					
120	FSR	2/24/2010	5/5/2009	n/a	3#		g	190330	G6845046	10841		
l		. ,		,								
424	500	10/0/2012	2/42/2222	Warm 74F to	2.54			202050	05045400	25025		
121	FSR	12/8/2012	3/18/2009	96F	3.5#		N	292050	G6846483	25825		
							Missin					
122	FSR	2/24/2010	3/20/2009	n/a	Missing		g	190223	G6847911	10847		
l		. ,		,								
		. /0 . /0 0	. /0=/000=	,								
123	FBC	1/31/2013	4/27/2009	n/a	2.5#		N	299018	G6850540	29706		
124	FSR	3/2/2010	4/9/2009	n/a	3.5#		N	190832	G6851218	10944		

r		1				ī		1			 	
125	FSR	7/18/2014	4/8/2009		4#		N	447522	G6851339	35859		
126	FBC	1/7/2011	4/22/2009	n/a	3.5		N	217968	G6852402	20295		
127	FSR	1/5/2012	5/5/2009	n/a	3#		Missin g	252560	G6853765	25947		
128	FBC	2/6/2013	5/8/2009	n/a	4#		N	299659	G6854367	29902	Gun has been in for repair previously.	
129	FBC	11/3/2010	5/8/2009	n/a	5#		N	209202	G6856996	15505		
130	Unexplained Discharge	5/7/2014	5/13/2009		3#		N	401067	G6857842	36068	Fired twice without finger being on trigger	
	2.33.161,62	5,1,100	5, 25, 2555		<u>G.</u>						on en 880	
131	FSR	9/17/2013	4/29/2009	n/a	4#		N	321319	G6858435	30251		
132	FSR	12/17/2010	4/29/2009	11/27/2010Anst ed, WV 25 to 35 degrees	3.5#		N	215224	G6858509	15277	Cut thumb on safety switch	

ı				1		1	1			I		
										Damaged		
										garage and		
										four		
133	FSR	3/25/2010	5/26/2009	n/a	3#	N	192779	G6860186	10682	wheeler		
										Damaged		
										garage and		
										four		
134	FSR	3/25/2010	5/26/2009	n/a	3#	N	192779	G6860186	15342	wheeler		
405	500	0/44/2044	5 /4 2 /2 2 2 2				465057	0.000.00	26447			
135	FSR	9/11/2014	5/13/2009		4.5	N	465357	G6860500	36117			
126	ECD	1 /0 /2010	F /4 /2000	- /-	2		105450	CC0C1C0C	10570			
136	FSR	1/8/2010	5/4/2009	n/a	3	N	185450	G6861686	10570			
137	FBC	12/11/2009	5/4/2009	n/a	3.5#	N	182921	G6861914	10741			
13/	FBC	12/11/2009	3/4/2009	II/a	3.5#	IN	102921	00001914	10741			
				12/28/2011loca								
138	FSR	2/23/2012	5/7/2009	tion unknown	3#	N	259627	G6862314	25967			
130	131(	2/23/2012	3/1/2003	tion unknown	5π	14	233027	00002314	23307			
											Videotaped	WANTS GUN
				12/4/200930							firing while	REPLACED,
				degreesMiami,							taking off	NOT
139	FSR	1/19/2010	5/19/2009	Ohio	3#	N	186710	G6866643	10593		safety	REPAIRED.
133	1311	1, 13, 2010	3,13,2003	01110	J.,	- 1	100710	30000073	10333		Juicty	MEI / MINED.
				12/3/2010Bigler								
				ville, PA 32 to 34								
140	FSR	12/17/2010	5/20/2009	degrees	4#	N	215236	G6867020	15530			
0 L	1311	12/11/2010	3/20/2003	achices	711		213230	30007020	10000			

ſ										1		
											3 Incidents	
			- 1 1	,							out of 74	
141	FSR	1/13/2012	5/21/2009	n/a	4#	N	253954	G6867324	25869		shots	
										Shot hole in		
										truck		
										floorboard,		
142	FSR	2/5/2015	5/20/2009		3#	N	491875	G6867504	40156	gun case and tire.		
142	1310	2/3/2013	3/20/2003		Jπ	IN	431873	00807304	40130	and the.		
											Happened	
											twice when putting	
											safety on,	
											and once	
							221523/22				when	
143	FSR	2/1/2011	6/8/2009	n/a	2.5#	N	1502	G6869260	20137		closing bolt	
											Got his rifle	
											back from	
											Remington, re: Re#	
											21502, and	
											it fired on	
											safety	
	500	2/42/2244	c /o /o oo	,	2 = 11		225072	0.00.00.00	20454		release 	
144	FSR	3/18/2011	6/8/2009	n/a	2.5#	N	226073	G6869260	20151		twice more.	
145	FSR	12/28/2010	6/3/2009	n/a	3.5#	N	216385	G6869716	20104			
				11/24/2013 In						Hole in the		
146	FSR	1/7/2014	6/12/2009	the barn	4.5#	N	332864	G6871761	30193	barn roof.		

r						1 1					
147	FBC	9/6/2012	6/10/2009	Warm and Cold IncidentsHappe ned Twice	4#	N	280643	G6871905	25976		
148	FSR	2/8/2013	6/10/2009	n/a	3.5#	N	299947	G6871905	30217		
149	FSR	1/7/2011	6/8/2009	n/a	3#	N	217879	G6872123	19925	Happened three times.	
ľ											
150	FBC	12/21/2010	7/6/2009	n/a	3.5#	N	215764	G6874601	15646		
151	FBC	12/21/2010	7/6/2009	n/a	3.5	N	215764	G6874601	20308		
152	FSR	2/24/2014	6/26/2009		3#	N	338721	G6875306	35624		
132	1310	2/24/2014	0/20/2003		3#		330721	00073300	33024		
	Fired while slung					Missin					
153	over shoulder	1/11/2012	6/25/2009	n/a	Missing	g	Missing	G6875478	25580		
				1/2/2011Bolivar							
154	FSR	1/19/2011	6/23/2009	, MO 11 to 39 degrees	3#	N	219657	G6876592	20094		
154	LOU	1/13/2011	0/23/2009	uegrees	3#	IN	213037	000/0332	20054		

r						. т					
155	FSR	1/25/2013	7/8/2009	n/a	2.5	Missin g	298215	G6876642	30010		
156	FBC	6/2/2014	7/9/2009	Extremely cold Nov. 2011 when the incident occurred	4.5	N	415730	G6877441	35924	Permanenet ringing in his ears. Called Remington, and was told there were nmo issues with the XMP triggers.	
157	FSR	12/16/2009	7/17/2009	n/a	4#		183430	G6879367	10625		
158	FSR	1/28/2011	7/31/2009	n/a	2#	N	221120	G6879765	20045		
159	FSR	12/21/2010	7/31/2009	n/a	3#	N	215688	G6880106	15457	Happened twice	
160	FSR	2/1/2010	7/13/2009	n/a	4#	N	186887	G6880141	10616		
161	FSR	1/31/2012	7/17/2009	n/a	3.5	N	256322	G6881516	25746	Two incidents	
162	Delay in firing after pulling trigger	4/7/2011	7/15/2009	n/a	4.5	N	228094	G6881696	20719		

1				1			1						
163	FSR	1/21/2011	7/27/2009	cold	3.5#		N	220003	G6883375	19933		Happened three times.	
164	FSR	12/16/2013	8/10/2009	11/30/2013loca	3#		N	331121	G6883669	29724		Three incidents.	
165	Fired without pulling the trigger	5/10/2012	8/6/2009	n/a	Missing		Missin g	Missing	G6884389	25752		Two incidentsK idd is an attorney representin g the gun owner (Ronald Coleman).	OWNERS DEMANDS TO RETURN ALL FIVE RIFLES BOUGHT FOR HIS GRANDSONS.
								-					
166	FBC	1/25/2010	7/27/2009	n/a	5.5#		N	187313	G6884603	10711		Happened four times.	
167	FSR	12/10/2014	8/6/2009	"FSR when it's cold"	n/a	n/a	N	479326	G6886443	39653			
168	FBC	1/23/2012	8/11/2009	n/a	4#		N	255586	G6888055	25926			
169	FSR	2/1/2013	8/24/2009	n/a	3#		N	299026	G6889241	29955			
											Shot wall of		
170	FBC	3/24/2015	9/2/9009		3#		n/a	497115	G6889651	40497	house		

						1		,			 	
171	FSR	3/31/2011	8/18/2009	n/a	4.5		N	227457	G6889918	20318		
172	FSR	3/31/2011	8/18/2009	n/a	4.5		N	227457	G6889918	20752		
173	Fired without touching trigger	2/3/2012	8/26/2009	n/a	2#		Missin g	257255	G6890138	25983		
174	FSR	4/15/2010	8/24/2009	n/a	3.5#		N	194124	G6890209	11046		
1/4	1310	4/ 13/ 2010	0/24/2003	11/ 4	3.5#		14	134124	00030203	11040		
175	FSR	2/4/2010	8/12/2009	n/a	3#		N	188398	G6891172	10606		
176	Fired while barely touching trigger	4/19/2011	8/7/2009	n/a	4#		N	229221	G6891302	20650		
177	Fires when safety is on	12/1/2011	8/7/2009	n/a	3#		N	248461	G6891423	25532		
				Cold Only happens when it is coldvideo							Rifle consumed by Remington in testingMr. Otto was given a new	
178	FSR	2/25/2014	9/11/2009	posted	3.5		N	338824	G6891613	36127	gun	
	Fired w/o pulling	0/00/	0/0=/		•							
179	trigger	3/20/2015	9/25/2009		3.5#		N	496991	G6893115	39923		

										I		
FSR	11/15/2010	8/28/2009	n/a	Missing		N	Missing	G6893334	19872			
ECD	11/19/2010	8/28/2009	n/a	2 5#		N	2100/15	G680333/I	15216			
1310	11/13/2010	6/20/2003	11/ 4	Σ.5π			210343	G0033334	13210			
												OWNER
												STATES
												REMINGTON
											Throo times	DID NOT REPAIR THE
												RIFLE, AND
			11/13/2010loca									DOES NOT
			tion of incident								was	THINK IT IS
FSR	12/13/2010	8/28/2009	unknown	3#		N	214283	G6893334	15575		unloaded	SAFE TO USE.
ECD EDG	11/12/2010	0/0/2000	/ -	F#		N.	240025	66003037	45202			w
FSK, FBC	11/12/2010	9/8/2009	n/a	5#		IN	210025	G0893937	15293		Cut finger	VV
											Did not	
											require	
											medical	
			-									
FCD	2/0/2011	0/26/2000		4.44		N.	225220	CC005C3C	20222			
FSK	3/8/2011	8/26/2009		4#		IN	225229	G6895626	20233		incidents.	
			burg, KY 24 to 40									
FSR	2/7/2011	9/4/2009	degrees	3#		N	222269	G6896369	20197			
	- 1 1	- 1 - 1 · · · · ·				_						
FSR	3/15/2011	9/4/2009	n/a	3.5#		N	225834	G6896382	20111			
											Three	
FSR	12/9/2013	9/23/2009	n/a	5.5#		N	330139	G6898407	29931		incidents	
	FSR FSR, FBC FSR FSR FSR	FSR 11/19/2010  FSR, FBC 11/12/2010  FSR 3/8/2011  FSR 2/7/2011  FSR 3/15/2011	FSR 11/19/2010 8/28/2009  FSR 12/13/2010 8/28/2009  FSR, FBC 11/12/2010 9/8/2009  FSR 3/8/2011 8/26/2009  FSR 2/7/2011 9/4/2009  FSR 3/15/2011 9/4/2009	FSR 11/19/2010 8/28/2009 n/a  11/13/2010location of incident unknown  FSR, FBC 11/12/2010 9/8/2009 n/a  11/19/2010Farg o, ND 10 to 33 degrees Cold 1/2/2011French burg, KY 24 to 40 degrees  FSR 2/7/2011 9/4/2009 n/a	FSR 11/19/2010 8/28/2009 n/a 2.5#  FSR 12/13/2010 8/28/2009 11/13/2010loca tion of incident unknown 3#  FSR, FBC 11/12/2010 9/8/2009 n/a 5#  FSR 3/8/2011 8/26/2009 n/a 5#  FSR 2/7/2011 9/4/2009 n/a 3.5#  FSR 3/15/2011 9/4/2009 n/a 3.5#	FSR 11/19/2010 8/28/2009 n/a 2.5#  FSR 12/13/2010 8/28/2009 11/13/2010location of incident unknown 3#  FSR, FBC 11/12/2010 9/8/2009 n/a 5#  FSR 3/8/2011 8/26/2009 11/19/2010Farg o, ND 10 to 33 degrees 4#  Cold 1/2/2011French burg, KY 24 to 40 degrees 3#  FSR 3/15/2011 9/4/2009 n/a 3.5#	FSR 11/19/2010 8/28/2009 n/a 2.5# N  FSR 12/13/2010 8/28/2009 11/13/2010loca tion of incident unknown 3# N  FSR, FBC 11/12/2010 9/8/2009 n/a 5# N  FSR 3/8/2011 8/26/2009 degrees 4# N  FSR 2/7/2011 9/4/2009 n/a 3.5# N  FSR 3/15/2011 9/4/2009 n/a 3.5# N	FSR 11/19/2010 8/28/2009 n/a 2.5# N 210945    11/13/2010location of incident unknown 3# N 214283   FSR, FBC   11/12/2010 9/8/2009 n/a 5# N 210025    FSR   3/8/2011 8/26/2009 degrees 4# N 225229	FSR 11/19/2010 8/28/2009 n/a 2.5# N 210945 G6893334  FSR 12/13/2010 8/28/2009 n/a 5# N 214283 G6893334  FSR, FBC 11/12/2010 9/8/2009 n/a 5# N 210025 G6893937  FSR 3/8/2011 8/26/2009 n/a 5# N 225229 G6895626  Cold 1/2/2011Fench burg, KY 24 to 40 degrees degrees degrees degrees and since the cold size of the c	FSR 11/19/2010 8/28/2009 n/a 2.5# N 210945 G6893334 15216  FSR 12/13/2010 8/28/2009 11/13/2010loca tion of incident unknown 3# N 214283 G6893334 15575  FSR, FBC 11/12/2010 9/8/2009 n/a 5# N 210025 G6893937 15293  FSR 3/8/2011 8/26/2009 o, ND 10 to 33 degrees 4# N 225229 G6895626 20233 Cold 1/2/2011French burg, KY 24 to 40 degrees 3/15/2011 9/4/2009 n/a 3.5# N 225834 G6896382 20111	FSR 11/19/2010 8/28/2009 n/a 2.5# N 210945 G6893334 15216  11/13/2010loca tion of incident unknown 3# N 214283 G6893334 15575  FSR, FBC 11/12/2010 9/8/2009 n/a 5# N 210025 G6893937 15293  FSR 3/8/2011 8/26/2009 degrees 4# N 225229 G6895626 20233  FSR 2/7/2011 9/4/2009 n/a 3.5# N 222269 G6896369 20197  FSR 3/15/2011 9/4/2009 n/a 3.5# N 225834 G6896382 20111	FSR 11/19/2010 8/28/2009 n/a 2.5# N 210945 G6893334 15216  Three times in a rowgun was unloaded  FSR, FBC 11/12/2010 9/8/2009 n/a 5# N 210025 G6893334 15575  Cut finger. Did not require medical attention. Two incidents.  FSR 3/8/2011 8/26/2009 degrees 4# N 225229 G6895626 20233 incidents.  FSR 2/7/2011 9/4/2009 n/a 3.5# N 222269 G6896382 20111  Three times in a rowgun was unloaded  N 214283 G6893334 15575  Cut finger. Did not require medical attention. Two incidents.

		1										
											Says 50	
											degrees or	
											below,	
											would not	
											do it at	
				ColdJanicki says							room	
				cut off is 50							temperatur	
188	FSR	12/3/2010	9/14/2009	degrees	4.5#	N	212224	G6898999	15475		e	
		, ,		J								
										Hole in the		
										floorboard		
										of truck.		
										Signed a		
										Remington		
										release to		
										get the		
										_		
										money to		
400	500	42/2/2040	0 /4 5 /2000	. 1.	2.54		242050	66004554	45500	repair		
189	FSR	12/2/2010	9/15/2009	n/a	2.5#	N	212058	G6901554	15599	truck.		
										Police		
										officer.Hole		
										in the		
										floorboard		
										of truck.		
										Three		
										incidentst		
				11/10/2010in						wo		
190	FSR	12/2/2010	9/15/2009	truck	2.5	N	212058	G6901554	20218	shooters.		
191	FSR	1/24/2012	9/16/2009	n/a	3.5#	N	255762	G6902880	25720			

192	FSR	12/10/2010	9/24/2009	12/26/2010Mr Young says the problem occurs when it is cold.	3.5#	N	214161/22 2314	G6903951	20596		Happened again after gun returned.	OWNER SAYS HE IS NOT SURE HE WANTS THE GUN BACKSAYS IT IS NOT WORTH GETTING HURT OVER.
193	FSR	11/22/2010	10/2/2009	n/a	2.5#	N	211267	G6906995	15263		Failed 3 out of 5 tries.	
194	FSR	1/13/2010	10/7/2009	n/a	3.5#	N	186042	G6907454	10830			
195	FBC	12/8/2010	10/7/2009	n/a	2#	N	213152	G6907475	15637			
196	Fired when shouldering the rifle	5/10/2011	10/26/2009	n/a	4#	N	231144	G6908507	20685			
197	FSR	2/7/2011	11/2/2009	n/a	4#	N	222285	G6913591	19878			
198	Fired without pulling the trigger when the gun was picked up.	12/7/2011	11/17/2009	n/a	5#	N	249473	G6916183	25327	Hole in wall and roof.		

ı												
	_			,			Missin					
199	FSR	11/12/2010	11/4/2009	n/a	3#		g	210169	G6918538	15586	Happened	
200	FBC	1/18/2011	11/12/2009	n/a	4.5		N	219436	G6918726	20272	twice.	
	0	_,,		, 4								
201	FBC	1/4/2012	12/4/2009	n/a	4#		N	252495	G6920578	25618		
202	FBC	1/17/2011	11/12/2009	n/a	4#		N	219300	G6920966	20246		
	-	, , ,	, , , , , , ,	, -								
203	FBC	8/5/2014	12/16/2009		n/a		n/a	455171	G6921232	36380		
204	FSR	1/24/2012	11/19/2009	n/a	4#		N	254723	G6921943	25932		
205	FBC	10/14/2011	11/18/2009	n/a	4.5#		N	243623	G6922925	25550		
203	FBC	10/14/2011	11/10/2009	II/ a	4.5#		IN	243023	00922923	23330		
206	FBC	1/24/2015	1/19/2010		2#	Sealant missing	n/a	487503	G6924264	39642		
200	FBC	1/24/2013	1/19/2010		2#	IIIISSIIIg	11/ a	467303	00924204	39042		
												OWNER ASKED FOR A
207	FSO	12/16/2010	12/22/2009	n/a	5#		N	214916	G6927022	15496		NEW GUN.
-		, ,, ,, ,,	, , , , , ,	, -	-							
			- 1 - 1	,								
208	FSR	2/16/2012	2/4/2010	n/a	3.5#		N	258837	G6929208	26011		

		1	1								1	
209	FBC	9/2/2014	12/22/2009		5#		N	462799	G6930687	36244		
210	FSR	3/8/2012	1/25/2010	n/a	3#		N	261242	G6934955	26018		
		-, -, -	, -, -	, -				_				
211	FSR	1/9/2012	3/10/2010	n/a	4#		N	253271	G6935258	25624		
		_, _,	5, 25, 2525	.,,								
212	FBC	9/22/2014	2/4/2010		3#		N	467130	G6937164	36031		
212	FBC	9/22/2014	2/4/2010		5#		IN	407130	00937104	30031		
				44/47/2040 84								
				11/17/2010Mt.								
		/ /	0/11/0010	Pleasant, PA 48								
213	FSR	11/16/2010	2/11/2010	to 52 degrees	4.5#		N	214386	G6938112	15324		
214	FSR	12/18/2014	1/27/2010		2.5#		N	481331	G6938891	40212		
												OWNER
												REQUESTED
												REFUND
												ONLY.
												DAUGHTER
												WILL NOT
												TOUCH THE
215	FBC	1/17/2011	1/29/2010	n/a	3#		N	219229	G6940058	20020		RIFLE AGAIN.
•	-	-	-			-					-	

216	FBC	6/8/2011	2/23/2010	n/a	5#	N	233242	G6940440	20694		
217	FSR	12/10/2010	2/3/2010	n/a	3#	N	214103	G6941066	15224		
21/	ron	12/10/2010	2/3/2010	11/ d	5#	IN	214105	G0941000	15224		
218	FSR	6/18/2013	2/14/2013	n/a	4#	N	313739	G6943633	30054		
	Accidental										
219	discharge	8/28/2013	8/28/2010	n/a	3.5#	N	319028	G6944968	30243		
222	500	0/20/2012	12/2/2010	,			270202	05045045	25724		
220	FSR	8/20/2012	12/3/2010	n/a	5.5#	N	279293	G6946045	25701		
221	FBC	9/1/2011	3/8/2010	n/a	5#	N	239779	G6950850	24240		
		37 27 2022	3, 3, 2020	, u	0		200770	0000000	2.2.0		
222	50.0	6 10 10011	2/5/2242	,	0.5		222242	06054300	20707		
222	FBC	6/8/2011	3/5/2010	n/a	3.5	N	233243	G6951200	20707		
				Warm 40F to							
223	FSR	10/24/2012	3/25/2010	65F	4.5#	N	286796	G6954322	25754		
			•								
224	FSR	4/17/2014	5/6/2010		3#	N	343595	G695584	35726		

r		1									
225	FSR	9/2/2011	3/23/2010	n/a	3.5#	N	239803	G6956968	25288		
223	1311	9/2/2011	3/23/2010	ii/ a	3.5#	IN	233603	00930908	23288		
226	FSR	3/8/2011	3/29/2010	n/a	4.5#	N	225232	G6957347	20158		
l		, ,	, ,	•							
227	FBC	5/13/2010	4/16/2010	n/a	5#	N	195800	G6964876	15246		
228	FSR	8/23/2011	4/27/2010	n/a	5#	N	238750	G6965284	23943		
222	500	6/24/2014	1/22/2212				420200	0.0000044	25570		
229	FSR	6/24/2014	4/23/2010		4#	N	429208	G6968311	35578		
230	FSR	1/25/2011	5/12/2010	n/a	5#	N	220588	G6969025	20253		
230	1310	1/23/2011	3/12/2010	iiy a	Jπ	IN	220300	00303023	20233		
231	FSR	6/13/2011	4/30/2010	n/a	3.5	N	233546	G6969130	20733		
ı				·							
232	FSR	10/16/2012	5/10/2010	n/a	3#	N	285608	G6971453	25694		
233	FBC	1/14/2011	6/1/2010	n/a	5#	N	219075	G6972126	19885		
234	FSR	4/14/2014	5/28/2010		4.5	N	343294	G6972160	35868		
234	гэп	4/ 14/ 2014	3/20/2010		4.5	IN	343234	003/2100	33000		

235	FSR	12/17/2013	5/18/2010	11/24/2013 location unknown	2.5#	Missin g	331256	G6974382	30133	Several incidents	OWNER SAYS HE WILL NO LONGER USE THE GUN BECAUSE OF THE SAFETY ISSUE.
236	FBC	5/18/2014	5/18/2010		4.5	Z	407524	G6974382	36235		OWNER WANTS GUN REPLACED. DOESN'T FEEL COMFORTABL E SHOOTING THIS RIFLE.
	. 30	3, 13, 101 .	3, 10, 2010				.0702.	3037.1002	00200		
237	FSR	11/25/2014	5/18/2010		5#	N	477691	G6974382	40402		
238	FSR & FBC	6/7/2011	6/29/2010	n/a	2.5#	N	233231	G6979079	20640		
239	Fired while on safety when unloading gun.	10/28/2011	7/2/2010	n/a	2.5#	N	245115	G6979486	25382		
240	FBC & FSR	3/22/2011	6/21/2010	n/a	3#	 N	226627	G6979615	20014		
241	FBC	9/11/2012	6/11/2010	n/a	3#	N	281653	G6980433	25589		

1											
242	FSR	6/15/2011	6/11/2010	n/a	3.5#	N	233746	G6981384	20677		
243	FSR	12/7/2010	6/29/2010	n/a	3#	N	212984	G6981781	15393		
										Photos unfire shells w impress in the fi	d ith ons ing
244	FSR	1/10/2012	7/1/2010	Warm 50's	5#	N	253336	G6983664	25894	cap.	
245	FSR	1/31/2012	7/14/2010	n/a	4.5	N	256782	G6987113	25595		
243	1 311	1/31/2012	7/14/2010	ii/ a	4.5	IN	230762	00987113	23333		
246	FBC	12/22/2010	7/23/2010	n/a	5.5#	N	215862	G6989650	20175		
247	Fired when raising the bolt	3/15/2011	7/29/2010	n/a	3#	N	225904	G6990868	20000		
248	Fired w/o pulling trigger	6/11/2014	7/28/2010		n/a		420338	G6991023	35588	Ammuni explode racke boltG went of house v touchi the trig	dc d un f in v/o
5	000.	-,,	1,20,2020		, ~		.2000	30002020	30000		5
249	FBC	12/7/2011	7/28/2010	n/a	4.5#	N	249358	G6991377	25420	Two incider	

1		I	I			1						ı	
250	FBC	11/22/2010	8/4/2010	n/a	4.5#		N	211140	G6992155	15252			
											Shot out back		
251	FSR	12/23/2014	8/6/2010		3#		N	481682	G6993869	40572	window of car.		
252	FSR	6/25/2014	10/5/2010		4.5		N	430533	G7000125	36389			
253	FBC	2/20/2014	9/7/2010		4#		N	338362	G7001864	35768			
254	FSR	11/15/2011	9/7/2010	n/a	2.5#		N	246995	G7003547	25406			
255	FBC	6/29/2014	1/10/2011		3.5		N	432576	G7017435	35756		Shot hole in ceiling	
256	FSR	2/5/2015	12/8/2010		5#		N	491738	G7026515	40610			
257	Fired without pulling the trigger	11/29/2011	4/15/2011	n/a	4#		N	248390	G7028525	25557			
258	Fired w/o touching the trigger	10/16/2014	2/8/2011		5#		N	471470	G7038656	35658			
259	FSR	3/19/2014	2/8/2011		4#		N	341073	G7039306	36316			
											Sht a hole in the		
	Fired w/o pulling	10/00/55	0 /00 /								ceiling and		
260	trigger	12/22/2014	2/23/2011		5.5#		N	481499	G70438844	40469	roof.		

ı												
261	FBC	2/26/2013	3/9/2011	n/a	4.5#	N	302049	G7045179	30316			
262	FBC	7/29/2011	3/3/2011	n/a	4#	N	236844	G7045857	25300			
	,,,,	1, -1, -1	2,0,2022	1,7,5								
263	FSR	11/6/2014	5/12/2011		4#	N	474542	G7048590	40001			
											Honorod F	
264	Fired when trigger touchednot pulled	6/20/2014	6/13/2011		n/a	N	427531	G7059966	36062		Happened 5 out of 11 rounds	
										Shot a hole in cab of		
	Fired w/o pulling									truck and rear		
265	trigger	12/31/2014	5/20/2011		n/a	n/a	n/a	G7060662	40285	window.		
266	FSR	8/21/2014	7/11/2011		6#	N	460735	G7067696	36089			
267	FBC	2/11/2014	7/23/2011		n/a	n/a	n/a	G7071449	39718	Shot hole in roof		
268	FSR	2/11/2014	7/13/2011		4#	N	337484	G7071562	36398			

									·			
FSR	1/16/2015	7/26/2011		5.5#		N	485631	G7075538	40301			
LCD.	10/24/2011	7/26/2011	n/a	2 5#		NI.	244411	C70774E0	25/12			
LOV	10/24/2011	7/20/2011	II/ a	3.3#		IN	244411	G7077439	25415			
											Two	
FBC	11/20/2013	8/16/2011	n/a	4#		N	328292	G7080537	29915		incidents	
		- 1- 1	,									
FBC	8/16/2013	8/8/2011	n/a	4#		N	318559	G7080978	29975			
FBC	9/10/2014	8/18/2011		5.5		N	464429	G7083151	35880			
										Shot hole in		
						Missin				gun range		
FBC	1/9/2014	8/17/2011	n/a	2.5#		g	333194	G7084409	29879	roof.		
FBC	2/22/2012	8/26/2011	n/a	3		N	259610	G7086996	25669			
										Charles India		
Fired w/o pulling												
trigger	1/26/2015	10/3/2011		5.5#		N	487889	G7098266	40086	doors		
	FBC FBC FBC FBC FBC FBC	FSR 10/24/2011  FBC 11/20/2013  FBC 8/16/2013  FBC 9/10/2014  FBC 1/9/2014  FBC 1/9/2014	FSR 10/24/2011 7/26/2011  FBC 11/20/2013 8/16/2011  FBC 8/16/2013 8/8/2011  FBC 9/10/2014 8/18/2011  FBC 1/9/2014 8/17/2011  FBC 2/22/2012 8/26/2011  Fired w/o pulling	FBC 1/9/2014 8/18/2011 n/a  FBC 1/9/2014 8/18/2011 n/a  FBC 2/22/2012 8/26/2011 n/a  Fired w/o pulling	FSR 10/24/2011 7/26/2011 n/a 3.5#  FBC 11/20/2013 8/16/2011 n/a 4#  FBC 8/16/2013 8/8/2011 n/a 4#  FBC 9/10/2014 8/18/2011 n/a 5.5  FBC 1/9/2014 8/17/2011 n/a 2.5#  FBC 2/22/2012 8/26/2011 n/a 3	FBC 11/20/2013 8/16/2011 n/a 3.5#  FBC 8/16/2013 8/8/2011 n/a 4#  FBC 9/10/2014 8/18/2011 n/a 2.5#  FBC 1/9/2014 8/17/2011 n/a 3  FBC 2/22/2012 8/26/2011 n/a 3	FSR 10/24/2011 7/26/2011 n/a 3.5# N  FBC 11/20/2013 8/16/2011 n/a 4# N  FBC 8/16/2013 8/8/2011 n/a 4# N  FBC 9/10/2014 8/18/2011 5.5 N  FBC 1/9/2014 8/17/2011 n/a 2.5# g  FBC 2/22/2012 8/26/2011 n/a 3 N  Fired w/o pulling	FBC 11/20/2013 8/16/2011 n/a 4# N 328292  FBC 8/16/2013 8/8/2011 n/a 4# N 318559  FBC 9/10/2014 8/18/2011 n/a 5.5 N 464429  FBC 1/9/2014 8/17/2011 n/a 2.5# g 333194  FBC 2/22/2012 8/26/2011 n/a 3 N 259610	FBC 11/20/2013 8/16/2011 n/a 4# N 328292 G7080537  FBC 8/16/2013 8/8/2011 n/a 4# N 318559 G7080978  FBC 9/10/2014 8/18/2011 n/a 4# N 464429 G7083151  FBC 1/9/2014 8/17/2011 n/a 2.5# Missin g 333194 G7084409  FBC 2/22/2012 8/26/2011 n/a 3 N 259610 G7086996	FSR 10/24/2011 7/26/2011 n/a 3.5# N 244411 G7077459 25413  FBC 11/20/2013 8/16/2011 n/a 4# N 328292 G7080537 29915  FBC 8/16/2013 8/8/2011 n/a 4# N 318559 G7080978 29975  FBC 9/10/2014 8/18/2011 n/a 2.5# g 333194 G7084409 29879  FBC 1/9/2014 8/17/2011 n/a 3 N 259610 G7086996 25669  Fired w/o pulling	FBC 11/20/2013 8/16/2011 n/a 4# N 328292 G7080537 29915  FBC 8/16/2013 8/8/2011 n/a 4# N 318559 G7080978 29975  FBC 9/10/2014 8/18/2011 n/a 4# N 318559 G7080978 29975  FBC 1/9/2014 8/17/2011 n/a 2.5# Missin g 333194 G7084409 29879 Shot hole in gun range roof.  FBC 2/22/2012 8/26/2011 n/a 3 N 259610 G7086996 25669  Fired w/o pulling Shot hole in glass fireplace	FBC 1/9/2014 8/17/2011 n/a 3.5# N 244411 G7077459 25413 Two incidents  FBC 11/20/2013 8/16/2011 n/a 4# N 318559 G7080537 29915 Two incidents  FBC 9/10/2014 8/18/2011 n/a 4# N 318559 G7080978 29975 FBC 1/9/2014 8/17/2011 n/a 2.5# Missin g 333194 G708409 29879 Shot hole in gun range roof.  FBC 2/22/2012 8/26/2011 n/a 3 N 259610 G7086996 25669 Shot hole in glass fireplace

Fired without												
pulling trigger	2/27/2012	10/10/2011	n/a	4#		N	260066	G7102917	25767			
			6/6/2012 in									
FSR	6/18/2012	11/17/2011	Florida	4#		N	272204	G7118702	25989			
												OWNER SAYS
			Warm									HE WILL NEVER TRUST
												THE GUN
FBC	3/26/2013	12/16/2011	55 degrees	4#		N	306089	G7125158	29968			AGAIN.
FSR	1/22/2014	12/7/2011		4.5		N	335058	G7127136	36254			
					Set							
					screws							
FBC	6/19/2014	12/22/2011		5.5	altered	n/a	426545	G7130523	36186			
FSR	6/6/2014	1/12/2012		n/a		N	417972	G7136840	36172			
Fired w/o pulling												
trigger	12/18/2014	1/27/2012		3.5#		N	481192	G7141805	40271			
FSR	2/10/2015	1/27/2012		5#		N	482372	G7142011	40246			
FBO	2/20/2014	2/2/2012		2.5		n/a	338474	G7142277	35798			
	FSR  FBC  FSR  FBC  FSR  FSR  FSR  FSR  FSR  FIred w/o pulling trigger  FSR	pulling trigger       2/27/2012         FSR       6/18/2012         FBC       3/26/2013         FSR       1/22/2014         FBC       6/19/2014         FSR       6/6/2014         Fired w/o pulling trigger       12/18/2014         FSR       2/10/2015	pulling trigger       2/27/2012       10/10/2011         FSR       6/18/2012       11/17/2011         FBC       3/26/2013       12/16/2011         FSR       1/22/2014       12/7/2011         FBC       6/19/2014       12/22/2011         FSR       6/6/2014       1/12/2012         Fired w/o pulling trigger       12/18/2014       1/27/2012         FSR       2/10/2015       1/27/2012	pulling trigger         2/27/2012         10/10/2011         n/a           FSR         6/18/2012         11/17/2011         6/6/2012in Florida           FBC         3/26/2013         12/16/2011         Warm Temperature 53-55 degrees           FSR         1/22/2014         12/7/2011	pulling trigger         2/27/2012         10/10/2011         n/a         4#           FSR         6/18/2012         11/17/2011         Florida         4#           FBC         3/26/2013         12/16/2011         Warm Temperature 53-55 degrees         4#           FSR         1/22/2014         12/7/2011         4.5           FBC         6/19/2014         12/22/2011         5.5           FSR         6/6/2014         1/12/2012         n/a           Fired w/o pulling trigger         12/18/2014         1/27/2012         3.5#           FSR         2/10/2015         1/27/2012         5#	pulling trigger         2/27/2012         10/10/2011         n/a         4#	pulling trigger         2/27/2012         10/10/2011         n/a         4#         N           FSR         6/18/2012         11/17/2011         Florida         4#         N           FBC         3/26/2013         12/16/2011         Warm Temperature 53- 55 degrees         4#         N           FSR         1/22/2014         12/7/2011         4.5         N           FBC         6/19/2014         12/22/2011         5.5         altered         n/a           FSR         6/6/2014         1/12/2012         n/a         N           Fired w/o pulling trigger         12/18/2014         1/27/2012         3.5#         N           FSR         2/10/2015         1/27/2012         5#         N	pulling trigger         2/27/2012         10/10/2011         n/a         4#         N         260066           FSR         6/18/2012         11/17/2011         Florida         4#         N         272204           FBC         3/26/2013         12/16/2011         Warm Temperature 53-55 degrees         4#         N         306089           FSR         1/22/2014         12/7/2011         4.5         N         335058           FBC         6/19/2014         12/22/2011         5.5         Set screws altered         n/a         426545           FSR         6/6/2014         1/12/2012         n/a         N         417972           Fired w/o pulling trigger         12/18/2014         1/27/2012         3.5#         N         481192           FSR         2/10/2015         1/27/2012         5#         N         482372	pulling trigger         2/27/2012         10/10/2011         n/a         4#         N         260066         G7102917           FSR         6/18/2012         11/17/2011         6/6/2012in Florida         4#         N         272204         G7118702           FBC         3/26/2013         12/16/2011         Warm Temperature 53- 55 degrees         4#         N         306089         G7125158           FSR         1/22/2014         12/7/2011         4.5         N         335058         G7127136           FBC         6/19/2014         12/7/2011         5.5         Set screws altered         n/a         426545         G7130523           FSR         6/6/2014         1/12/2012         n/a         n/a         N         417972         G7136840           Fired w/o pulling trigger         12/18/2014         1/27/2012         3.5#         N         481192         G7141805           FSR         2/10/2015         1/27/2012         5#         N         482372         G7142011	Pulling trigger   2/27/2012   10/10/2011   n/a   4#   N   260066   G7102917   25767	Pulling trigger   2/27/2012   10/10/2011   n/a   4#   N   260066   67102917   25767	Pulling trigger   2/27/2012   10/10/2011   n/a   4#   N   260066   G7102917   25767

Three
Three
Three
incidents
<u>in</u>

		1		1			-				1	
294	Fired without touching trigger	12/11/2012	4/19/2012	11/17/2012hap pened in trucklocation unknown	3.5#	N	292419	G7169353	25904	Shot in right arm when gun fell in his truck. Damage to truck and wife's car.		
295	FBC	3/8/2013	4/12/2012	n/a	3.5	N	303290	G7174373	29847			
296	FBC	11/24/2014	4/19/2012		n/a	n/a	n/a	G7176861	40495			
						Missin						
297	FSR	12/12/2011	Missing	n/a	Missing	g	Missing	n/a	25484			
298	FSR	9/30/2013	11/6/2006	n/a	1.5#	Missin g	322575	RMEF7233	29791			
299	FSR	6/19/2014	2/14/2014		n/a	n/a	406105	RR00766E	35899			
300	FSR	1/22/2014	4/23/2012		3.5	N	334960	RR01011A	36363		Seven instances	
301	FBC	4/23/2015	10/1/2014		4.5#	n/a	498767	RR01415F	40203			

		1	ı								
										Shot hole in	
302	FBC	10/28/2014	4/26/2012	11/7/2013 in	3.5#	N	472867	RR04323A	40619	deer stand.	
				South Dakota,							
				exact location							
303	FSR	12/4/2013	5/9/2012	unknown	4#	N	329532	RR04726A	30270		
											OWNER
											WANTS THE
											GUN
304	FBC	9/2/2014	5/13/2013		4#	N	462752	RR06407C	36287		REPLACED.
305	FSR	4/21/2015	6/4/2012		2.5	N	498612	RR08880A	39984		
306	FSR	4/28/2015	3/5/2014		2.5#	n/a	498909	RR1101E	40074		
										Shot hole in	
				12/8/2013 Gun						ceiling and	
				fired inside						bathroom	
307	FSR	12/23/2013	5/10/2012	apartment	4.5#	N	331923	RR11121A	30121	door.	
308	FBC	10/1/2014	8/11/2014		5#	N	469316	RR11152F	35823		
		-, , :	-, ,								
309	FBC	10/1/2014	7/22/2014		4#	N	469322	RR11465F	35832		
309	I DC	10/1/2014	1/22/2014		4#	IN	+03322	WITTHOOL	33032		

ĺ											
310	FBC	10/1/2014	5/9/2012		4#	N	469237	RR11525A	36051		
310	150	10/1/2014	3/3/2012		711	1	403237	MILISZSA	30031		
											Does not want
311	FBC	3/10/2015	5/9/2012		3#	N	495467	RR11874A	39813		the gun back.
312	FBC	8/27/2014	10/28/2013		4.5	N	461697	RR14268E	35541		
313	FBC	10/1/2014	12/4/2012		4.5	N	469128	RR14583B	35677		
						Missin					
314	FSR	12/13/2013	5/21/2012	n/a	Missing	g	Missing	RR14896A	30110		
										Shot hole in	
										carpet and concrete in	
315	FBC	8/4/2014	5/17/2012		4#	N	453869	RR15014A	40146	living room.	
										Shot a hole in the gun	
										safe and	
	Fired w/o pulling									another	
316	trigger	12/22/2014	1/4/2013		4.5#	N	481490	RR18907B	40375	gun.	

-		1										
317	FBC	1/14/2015	5/24/2013		5#	N	485312	RR19631C	40515			
318	FSR	1/11/2013	5/29/2012	n/a	4.5#	N	296325	RR21734A	29871			
319	FBC	3/20/2015	6/5/2013		3.5#	N	496994	RR21883C	40324	Shot a hole in kitchen table, stool and wall.	Owner says he will take it to small claims court.	
320	FBC	4/13/2015	12/18/2014		5#	Ν	498169	RR23488F	40257			
321	FEB	5/11/2015	11/1/2013		4.5#	N	499441	RR23685E	39761	Shot hole in door of truck.		
322	FSR	5/6/2014	6/6/2012		5#	n/a	395609	RR25297A	35994			
322	1311	3/0/2014	0/0/2012		J₩	11/ a	393009	NN2J237A	33334			
323	FSR	3/13/2013	6/19/2012	n/a	4.5#	N	304577	RR26257A	29908			
324	FBC	12/18/2013	5/28/2013	n/a	6#	N	331345	RR26369C	29755			
325	Delayed firing	11/21/2014	6/9/2012		5.5#	N	477348	RR26889A	39932			

							-				· · · · · · · · · · · · · · · · · · ·	
326	FSR	12/8/2014	6/22/2012		n/a	N	478812	RR27998A	39804			
										Shot hole in	Owner	
										ceiling, floor,	threaening lawsuit.	
										toiletwat	Refused to	
							_			er damage	send gun to	
327	FBC	11/10/2014	6/6/2013		n/a	n/a	n/a	RR29247C	40310	as well.	Remington.	
328	FBC	8/23/2012	6/18/2012	n/a	4.75#	N	279687	RR30199A	25644			
	Fired w/o touching											
329	the rifle	6/23/2014	1/2/2012		4\$		428132	RR30858B	35617			
330	FSR	3/25/2014	6/17/2013		4.5	N	341645	RR30899C	35840			
331	FSR	12/13/2014	10/9/2013		3.5#	N	480313	RR32883C	40354			
332	FSR	4/9/2013	4/8/2013	n/a	4#	N	307417	RR32886A	29945			
											Cam aut bia	
333	FSR	12/17/2014	2/7/2013		2.5#	n/a	480752	RR33499B	40426		Son cut his thumb.	
											Has two	
	Fired w/o pulling									Shot hole in awning of	holes in his right ear	
334	trigger	2/2/2015	6/18/2012		n/a	n/a	n/a	RR33725A	39897	his house.	drum.	
225	500	44 /25 /205	6 /22 /224		,	,	,		20005			
335	FSR	11/26/2014	6/22/2012		n/a	n/a	n/a	RR33897A	39999			

r							1				
336	FBC	1/29/2015	1/8/2013		4.5#	N	489367	RR34022B	39751		
337	FBC	1/8/2014	8/8/2013		3.5	N	332977	RR34949C	36412		
338	FBC	2/11/2014	8/8/2013		4#	N	337361	RR34949C	36420		
										Shot hole in	
339	FBC	1/8/2013	8/24/2012	n/a	5#	N	295421	RR39187A	30032	brother's house	
340	Fired w/o pulling trigger	2/10/2015	6/20/2013		2#	n/a	492387	RR39228C	39678		
				<b>-</b>						Charles I.I.	
341	FBC	10/10/2014	2/7/2013	Trigger assembly had been changed	5#	N	448967	RR41226B	40014	Shot hold in fan and ceiling	
	-	-, -, -	, ,								
342	FBC	6/24/2013	1/29/2013	n/a	Missing	Missin g	Missing	RR41404B	30114		
343	FSR	8/26/2013	7/18/2012	n/a	4#	N	319065	RR42107A	30163		

344	FSR	2/12/2014	7/16/2012		3.5	N	337551	RR42158A	36078		Constant ringing in ear, loss of hearingha s a video of FSR	
345	FSR	2/4/2015	7/16/2012		4.5#	Z	489774	RR42158A	40223	Shot hole in deer blind.		Ringing in his right ear. Has asked Remington for compensation.
343	ran	2/4/2013	7/10/2012		4.5#	IN	403774	NN42136A	40223	deer billiu.		compensation.
346	FBC	11/18/2014	7/22/2013		n/a	n/a	n/a	RR42365C	39789			
347	FSR	12/14/2012	6/29/2012	n/a	3#	N	292947	RR42395A	25687			
348	FBC	1/30/2013	7/17/2012	n/a	5#	N	298738	RR42955A	29815			
349	FBC	11/20/2012	7/18/2012	n/a	3.5#	N	289945	RR43347A	25663			OWNER DEMANDED NEW GUN.
350	FBC	3/1/2013	8/27/2012	n/a	3.5#	N	302715	RR43564A	29840		Two incidents	
351	FSR	3/7/2013	8/2/2012	2/24/2013locati on unknown	3#	N	303851	RR44012A	29806			
352	FSR	1/24/2014	8/6/2012		3#	N	335334	RR45269A	35598			
353	FSR	11/21/2012	7/23/2012	11/3/2012locati on unknown	4.5#	N	290108	RR45325A	25735			

				1								
354	FBC	4/15/2015	8/2/2012		4.5#	N	498447	RR45574A	39913	Shot hold in blind		
355	FSR	12/12/2014	7/26/2012		n/a	n/a	n/a	RR46719A	40084			
333	ran	12/12/2014	7/20/2012		II/ a	II/ a	II/ d	NN40/19A	40064			
356	FSR	8/11/2014	10/15/2012		2.5	N	457088	RR48070A	36225			
		5,,										
357	Unexplained Discharge	6/2/2014	2/1/2013		n/a	n/a	425980	RR49048B	35817			
	•										Two	
358	FSR	12/30/2013	8/7/2012	n/a	4#	N	332222	RR49947A	29831		incidents	
359	FSR	12/30/2013	8/7/2012		4#	N	332222	RR49947A	35668			
		0 /5 /00 10	- / - 0 / - 0 - 0	8/18/2013locati		Missin						
360	FSR	9/5/2013	7/19/2013	on unknown	4#	g	320305	RR52525C	29774			
361	FSR	1/28/2013	8/10/2012	n/a	4#	N	298477	RR52624A	29923			
	Fired w/o pulling											Ringing in his
362		2/13/2015	11/29/2012		n/a	n/a	n/a	RR55978A	40241			ear.
JU2	C1 199C1	2/ 13/ 2013	11/23/2012	<u> </u>	11/ 4	11/4	11/ 0	111333707	102-11			cui.

			·				1				· · · · · · · · · · · · · · · · · · ·	
363	FSR	1/20/2015	3/7/2013		4.5#	N	486639	RR56420B	40289			
											Trigger was	
											punch	
											marked indicating	
											recall has	
264	500	10/22/2011	4 /2 4 /2 24 4		6.11		4705.45	BB566055	25554		been taken	
364	FBO	10/22/2014	1/24/2014		6#	N	472545	RR56695E	35551		care of	
365	FBC	9/20/2013	3/6/2013	n/a	3#	N	321706	RR60378B	29765			
200	FRS	7/2/2014	2/25/2012		2#	N	435004	RR63593B	36108			
366	FKS	7/2/2014	2/25/2013		2#	N	433004	KKOSSSSB	20109	Shot hole		
										through a	_	
										tool box and wall in	Does not want the	
367	FBC	1/28/2015	8/8/2013		5#	N	488804	RR66940C	40180	house.	rifle back.	
368	FBC	1/31/2014	8/8/2013		4#	N	336236	RR68670C	36022			
		_,,	5, 5, 2525									
		0/10/22:-	0/10/22:2									
369	FBC	3/16/2015	9/18/2012		4.5#	N	496261	RR70677A	39826			

270	FCD	1/21/2011	0/20/2012		4.44			224042	DD700434	25725			
370	FSR	1/21/2014	9/28/2012		4#		N	334912	RR70912A	35735			
	Fired without												
371	touching the trigger	8/5/2014	8/28/2013		3.5		N	455135	RR76311C	35777			
0.1		3,3,202	0, 20, 2020		0.0		.,	.00200		00777			
											Shot hole in		
											window		
											casing and		
											metal		
272	Fired w/o pulling	F /4 C /2 O 4 4	2/24/2012		/		/-	224000	DD04047D	40001	siding of		
372	trigger	5/16/2014	3/21/2013		n/a		n/a	331089	RR81947B	40601	house		
373	FSR	9/9/2014	3/12/2014		5.5		N	464152	RR82249E	35978			
		, ,	, ,								Shot out a		
											window		
											and his		
											hunting		
374	FBC	4/30/2015	3/28/2013		4.5#		N	499015	RR82406B	39943	bow		
												Incident	
												occurred 3 out of 5	
375	FBC	4/6/2013	2/6/2013	n/a	2.75#		N	309191	RR89082A	29698		times.	
3/3	Fired w/o pulling	4/0/2013	2/0/2013	11/ a	2.75#		IN	303131	MNOJUOZA	23038		times.	
376	trigger	2/5/2015	4/2/2014		4.5#		N	491729	RR92367E	40115			
377	FBC	11/12/2014	9/25/2014		3#	n/a	N	476068	RR97518E	39661			
378	FBC	2/2/2015	5/8/2013		4#		N	490509	RR975419B	39867			
3,0	1 DC	2/2/2013	3/0/2013		711	<u> </u>	- 14	-+50505	11113737111	33007			

								1			1	1	
379	FBC	8/13/2014	9/18/2013		4.5		N	458082	RR98326C	35850			
						Origianl trigger							
						assembl							
						y set						Damaged	
380	FSO	12/13/2013	2/10/2004		2.5	screws altered		330784	S6488401	36148		his truck and trailer	
			, ,										
381	FSR	8/24/2009	10/17/2005	n/a	2.25#		N	173632	S6540548	10825			
							Missin						
382	FBC	11/6/2013	3/3/2006	n/a	Missing		g	Missing	S6556777	30189			
383	FSR	1/26/2011	6/5/2006	n/a	4#		N	220729	S6561540	19910			
				trigger had been tightened by									
384	FSR	12/2/2014	6/30/2006	gunsmith	n/a		n/a	n/a	S6563183	40011			
385	FSR	1/2/2014	7/20/2006		2.5		N	332426	S6563294	35955			
											Damage to		
											truck		
				Temperature							floorboard, frame and		
				around 32							radiator\$		
	Fired w/o pulling	- t- to :	- 1 1	degrees and	_						768 to		
386	trigger	6/8/2015	8/17/2006	snowing	4#		N	500402	S6566143	39745	repair		

			T								 	
387	FBC	12/6/2011	11/7/2006	n/a	3#		N	248218	S6566174	25364		
388	FSR	2/21/2012	8/22/2006	n/a	4#		N	259225	S6567929	25888		
389	FSR	2/23/2009	5/24/2006		4.5#		N	162584	S65682780	9343		
390	FSR	2/23/2009	5/24/2006	n/a	4.5#		N	162584	S6568280	PSO9343		
391	FSR	2/3/2009	5/25/2006	1/15/2009specif ic location unknown	2.5#		N	161002	S6568331	20421	Three incidents.	
392	FSR	1/11/2008	11/3/2006		2.5#	Trigger Pull	N	139607	S6571612	9359	Fired six times when safety released	OWNER DEMANDED NEW GUN
393	Unexplained Discharge	5/28/2014	7/10/2006		4.5		N	413568	S6573337	35890		
											Happened once in 2006 and twice in	
394	FSR	2/28/2008	7/11/2006		6#		N	142279	S6574111	9383	2007	
395	FSR	1/8/2010	11/28/2006	n/a	5.5#		N	185452	S6574607	11109		
396	FSR	11/28/2012	10/5/2006	Cold Only happens when temp. is around 32 degrees	4#		N	290648	S6575237	26004		

1				1				1					
						No sealant on Adjustin						Fired twic e	
						g						when safety	
397	FSR	12/28/2007	8/17/2006		3.5#	Screws	N	138690	S6576868	9351		released	
	Fired w/o pulling										Shot hole in roof of		
398	trigger	1/27/2015	10/3/2006		3#		N	488262	S6577623	39770	truck.		
399	FBC	2/25/2014	9/11/2006		1#	Screw altered	n/a	338764	S6579845	36372			
	127		3, ==, ==0				.,,					Shot hole in	
400	FBC	9/24/2014	9/7/2006		4.5		N	467572	S6580000	35686		wall	
						Set							
						screws						While deer	
						altered						hunting gun fired when	
						to lighted						safety	
						trigger						turned	
401	FSR	12/28/2007	11/6/2006	n/a	3#	pull	N	138816	S6585150	9347		ontwice	
							Missin						
402	FSR	12/4/2010	1/16/2007	n/a	3.5#		g	212674	S6587747	15383			
											Hole in floorboard		
1	FBC	12/15/2007	11/28/2006		6#		N	138397	S6588599	8830	of truck		
	-	, -,	, -,		-								
	Finad/a mII'												
2	Fired w/o pulling trigger	1/29/2015	3/12/2007		3#		N	489037	S6594220	40626			
-	11.19gc1	1, 23, 2013	3/ 12/ 2007		5π		- 14	403037	30337220	40020			
3	FBC	12/13/2011	1/4/2007	n/a	5.5#		N	250232	S6594374	25525			

			Ī						1	ı	1
4	Fired w/o pulling trigger	2/9/2015	9/23/2008		4.5#	N	492389	S6597538	40460		
·	680.	2,3,2023	3/10/1000				.52005	00007.000	10.00		
5	FSR	12/13/2010	2/3/2007	n/a	2.2#	N	214023	S6597739	15484		
5	131(	12/13/2010	2/3/2007	iiy a	Σ.Ζπ	IN	214023	30337733	13464		
6	FBC	1/28/2010	2/26/2007	n/a	4#	N	187703	S6599888	10643		
	Unexplained	- 1 1				,					
7	Discharge	5/21/2014	3/23/2007		4#	n/a	409260	S6604431	36005		
8	Fired without pulling the trigger	2/24/2011	3/26/2007	n/a	4.5	N	224268	S6607482	20278		
Ū	panning are arigher		3, 23, 233.	,				00007.102	20270		
										Shot a hole in his truck	
										wheel and	
9	FSR	12/15/2014	3/28/2007		n/a	n/a	n/a	S6607507	39837	tire	
						N 41 1 -					
10	FBC	1/18/2011	6/12/2007	n/a	Missing	Missin g	Missing	S6609406	25917		
				·		_ Ŭ	<u> </u>				
11	FSR	1/16/2008	7/18/2007		4#	N	139923	S6613730	9366		
	. 5	_, _0, _00	., 20, 2001				100010	30020.00	3333		
12	FBC	7/31/2012	7/9/2007	n/a	1.5#	Missin g	276382	S6615869	25876		
14	1 00	7/31/2012	77372007	11/ a	1.J#	<u> </u>	270302	20012003	23070		
13	FSR	12/2/2013	7/12/2007		n/a	n/a	n/a	S6620131	40071		
13	1 311	12/2/2013	1/12/2007		11/ a	11/ a	11/ a	30020131	400/1		

						•						
14	FSR	1/21/2015	9/17/2007		3.5#		N	486795	S6625034	40587		
						Pull						
						screw						
15	FSR	1/28/2010	9/19/2007	n/a	4#	altered		187808	S6625117	10819		
	Fired while on						Missin					
16	safety	8/15/2011	10/26/2007	n/a	5#		g	237939	S6631560	25390		
											Happened twice with	
											two	
											different	
17	FBC	4/14/2010	10/5/2007	n/a	2.5		N	194012	S6631971	20437	operators.	
	Fired without										Three	
18	pulling the trigger	8/29/2011	11/30/2007	n/a	4.5#		N	239266	S6637313	25486	incidents.	
10	FSR	7/22/2012	12/12/2007		n /a		n /a	n /n	S6639721	40143		
19	FSK	7/23/2013	12/13/2007		n/a		n/a	n/a	30039721	40143		
											Shot hole in	
											1999 Ford	
20	FSR	9/23/2014	4/14/2008		3.5		N	467599	S6649813	36040	Ranger	
21	FSR	12/3/2010	4/11/2008	n/a	3.5#		N	212374	S6650147	15376		
22	FBC	11/4/2010	4/22/2008	n/a	3.5#		N	208626	S6650372	15443		
	150	11/ 7/ 2010	7/ 22/ 2000	11/ α	3.5#			200020	30030372	13-7-13		
							Missin					
23	FBC	10/16/2012	4/14/2008	n/a	4.5#		g	285839	S6650476	25601		

						Missin					
24	FSR	2/7/2012	5/14/2008	n/a	1.5#	g	257731	S6653059	30079		
		. ,		·		J					
25	FCD.	1/10/2011	F /20 /2000	n /n	N dia sira s	Missin	222026	CCCE 4077	25052		
25	FSR	1/19/2011	5/30/2008	n/a	Missing	g Missin	222026	S6654977	25953		
26	FSR	1/22/2013	9/5/2008	n/a	1#	g	297652	S6673473	29863		
										Hole in	
										truck, and	
	Fired when raising									destroyed brake	
27	the bolt	11/18/2009	10/23/2008	n/a	Missing		Missing	S6677880	10564	caliber	
				11/16/2009Kalk							
				aska, MI19 to						Hole in	
28	FBO	11/24/2009	10/23/2008	46 degrees	5#	N	181335	S6677880	10559	truck	
29	FSR	3/24/2011	5/14/2009	n/a	4#	N	226724	S6687582	19899		
30	FSR	12/28/2010	5/14/2009	n/a	3#	N	216404	S6689045	15426		
31	FSR	12/28/2010	5/14/2009	n/a	3#	N	216404	S6689045	20055		

32	FBC	3/8/2011	4/14/2009	n/a	4#	N	225282	S6691208	20189		
ľ				-							
										Purchased	
										two rifles,	
33	FSR	12/11/2009	5/20/2009	n/a	3.5#	N	182892	S6695663	11096	both do it	
"	1310	12/11/2005	3/20/2003	11/ α	3.311	.,	102032	30033003	11030	both do it	
	Fired without										
24		12/15/2010	C /4 /2000	/	24	N.	24.4700	55505147	15426		
34	pulling the trigger	12/15/2010	6/1/2009	n/a	2#	N	214798	S6696147	15436		
35	FSR	3/9/2012	7/13/2009	n/a	3#	N	261360	S6696479	25882		
36	FSR	10/11/2010	5/27/2009	n/a	2.5#	Υ	205793	S6697267	15370		
37	FSR	3/13/2015	6/15/2009		2#	N	496633	S6697988	39779		
	Fires when trigger is	-, -, -	, , ,								
	pulled with bolt										
38	open	1/30/2012	6/23/2009	n/a	3.5#	N	256635	S6699370	25760		
, J	орен	1/30/2012	0/23/2003	1η α	3.311	- ' '	230033	30033370	23700		
39	FSR	8/24/2010	9/4/2009	Warm 50's	3#	N	201307	S6700049	15272		
39	LOU	6/24/2010	9/4/2009	Walli 303	3#	IN	201307	30700049	13272		
				,							
40	FSR	1/13/2011	9/4/2009	n/a	3.5	N	218777	S6700063	19968		
41	FSR	12/19/2014	8/28/2009		3.5#	N	481322	S6702723	39900		
										•	

				1		1				1		
42	FBC	5/15/2012	7/28/2009	n/a	3#		N	267429	S6702859	25637		
43	FSR	12/30/2010	8/28/2009	n/a	4#		N	216751	S6704623	19918		
44	FBC	8/26/2011	8/3/2009	n/a	4#		N	239163	S67054407	25449		
45	FSR	6/15/2011	8/21/2009	n/a	3.5		Ζ	233742	S6705484	20744		
46	FSR	12/10/2013	8/20/2009	n/a	3#		N	330323	S6705715	30000	Two incidents	
47	FSR	3/5/2013	8/21/2009	n/a	2.5#		N	303330	S6706127	29742	Two incidents	OWNER SAYS HE CAN NOT TRUST THE GUN AGAIN.
48	Fires with safety on	12/12/2011	8/24/2009	n/a	3#		N	249828	S6706986	25452	Five incidents.	
49	FSR	12/2/2013	9/16/2009	n/a	4.5#		N	329185	S6708613	30261	meraenes.	
43	1311	12/2/2013	3/10/2003	ii/a	4.5#		IN	323183	30708013	30201		
50	FBC	12/10/2010	9/3/2009	n/a	Missing		N	213790	S6708648	15517		
51	FSR	2/7/2013	9/17/2009	Left the gun in truck overnight, and temp. dropped down to 20 degrees.	3.5#		N	299832	S6709895	30172	Two incidents	
				Ŭ								
52	FSR	1/24/2014	9/22/2009		3.5		N	335398	S6710992	35569		
53	FBC	11/2/2010	11/10/2009	10/25/2010loca tion unknown	3.5		N	208939	S6714315	15614		

1				1								
54	FBC	11/23/2010	1/20/2010	n/a	3#		N	211335	S6715747	15363		
55	FBC	12/17/2014	2/25/2010		2.5#	Pull screw altered	N	480674	S6716267	40415		
56	FSR	11/17/2011	6/29/2010	n/a	3.5#		N	247377	S6717529	25343		
57	FSR	12/19/2013	2/15/2010	Happened when cold	3.5#		N	331586	S6717705	29716		
58	FSR	3/25/2014	2/15/2010		4#		N	341512	S6717705	35937		
59	FBC	5/8/2012	1/22/2010	n/a	2.5#		Missin g	266897	S6717753	25960		
60	FBC	6/27/2013	2/5/210	n/a	2.5#		N	314308	S6719747	29985		
61	FBC	12/16/2013	4/21/2010	n/a	3.5		N	331044	S6723366	29735		
62	FSR	8/8/2013	6/8/2010	·	n/a		n/a	n/a	S6726141	40492		

i		Ī				1					
63	FSR	12/7/2010	6/14/2010	n/a	4.5#	N	213110	S6731654	15539		
64	FBC	4/1/2015	8/17/2010		n/a	N	497681	S6732078	39840		Does not want the gun back.
65	FSR	11/18/2010	6/11/2010	n/a	Missing	Missin g	Missing	S6732204	15527		
66	FSR	11/28/2011	7/19/2010	n/a	2.5	Б N	248061	S6736723	25356		OWNER WANTS GUN REPLACED BECAUSE HE CAN NOT TRUST IT AGAIN.
	-	, -, -	, ,, ,	, -							
67	Fired with safety on	8/21/2014	7/23/2010		5.5	N	460471	S6739468	35709		
68	Fired on bolt opening	11/10/2014	9/21/2010		4#	N	475151	S6740104	40440	Shot out back glass in truck and two camper windows.	
69	Fired without pulling the trigger	12/8/2010	9/8/2010	n/a	Missing	Missin	Missing	S6745430	15452		
70	FBC	12/20/2010	9/14/2010	12/18/2010inci dent happened in hotel	Missing	Missin g	Missing	S6745623	15249	Shot hole in the door of hotel.	

						1					
71	FBC	12/30/2010	11/2/2010	n/a	Missing	Missin g	Missing	S6749000	20270		
										Owner	Owner says debris from
										refused to send the	the shot is in his chest.
72	FSR	12/19/2014	12/14/2010		n/a	n/a	n/a	S6752539	40244	gun to Remington.	Shot into the ground.
73	FSR	3/11/2014	3/26/2011		3#	N	340244	S6753921	35609		
		, ,	, ,								
74	FSR	1/30/2015	3/29/2011		n/a	n/a	n/a	S6760893	39721		
75	Fired with safety on	2/12/2014	6/8/2011		3.5	N	337582	S6769759	36278		
	Failed aa 2" drop										
76	test after setting trigger @ 3 lbs.	3/28/2012	7/13/2011	n/a	3#	N	262957	S6770428	25714		
77	Fails to fire when trigger is pulled	10/24/2013	12/9/2011	n/a	3.5#	N	325130	S6775632	30069		
, ,	trigger is pulled	10/24/2013	12/3/2011	11/ 0	3.5#	I N	323130	30773032	30003		
78	FSR	1/18/2013	10/21/2011	n/a	4#	N	297101	S6777539	29994		
							278194/28				
79	FBC	8/13/2012	12/13/2011	n/a	4.5#	N	2317	S6781235	25938		

1							1				
80	FBC	1/28/2013	4/2/2012	n/a	5#	N	298482	S6788957	30061		
00	TBC	1/20/2013	4/2/2012	11/ 4	Jπ	IN	230402	30700337	30001		
81	FBC	5/27/2014	3/29/2012		4#	N	411366	S6793846	36177		
01	TBC	3/2//2014	3/29/2012		4#	IN	411300	30733840	30177		
82	FSR	12/10/2012	4/3/2012	n/a	3.5#	N	292261	S6794313	25831		
02	1310	12/10/2012	7/3/2012	11/ 4	3.311	- 1	232201	30734313	23031		
00	FDC	4 /47 /2042	10/24/2012	/ -	2.5	Missin	200010	66706700	20156		
83	FBC	1/17/2013	10/24/2012	n/a	3.5	g	296810	S6796790	30156		
84	FSR	11/26/2012	8/2/2007	n/a	4.5#	N	290255	S7664804	25573		
	Fired w/o pulling										
85	trigger	1/12/2015	5/27/2010		4.5#	N	484971	T6270714	39794		
	Fires only when bolt										
86	is partially open	11/4/2011	9/23/2010	n/a	4.5	N	246045	T6270729	25437		
-	1 7 - 1		, ,	, -	_						
		10/10/100:-	= /o . /o o . =	,							
87	FSR	12/12/2010	5/21/2010	n/a	Missing	N	214201	T6271263	15286		
				12/4/2010Canaj							
				oharie, NY 28 to							
88	FSR	12/28/2010	12/27/2006	32 degrees	2.3#	N	216344	TT008532	19950		h

S6568666	
S6583063	
S6578744	
G6710198	
S6583624	
S6692878	
S6628772	
G6976960	
S6597736	
G6880106	
G6855483	
G6680467	
G6969130	
G7002697	
S6726023	
G6830287	
S6574619	
C6471803	
G6864847	
S6717705	

Investigation Photos

G6673556.d ocx

G6705329.d ocx -

G6730719.d

<u>OCX</u>

G6740364.d

<u>OCX</u>

G6846483.d

G6871905.d

<u>OCX</u>

\_

G6876642.d

G6891613.d

G6893334.d

<u>OCX</u>

G6893334.d

OCX

G6896369.d

G6902880.d ocx <u>G6935258.d</u>

G6971453.d ocx

G6979079.d ocx G6981384.d

<u>OCX</u>

G6983664.d ocx G7003547.d ocx <u>G7125158.d</u> <u>ocx</u> RR21734A.d ocx RR42395A.d ocx

<u>S67000049.</u> <u>docx</u> S6578744.d

<u>OCX</u>

S6597736.d

OCX

G6855483.d